



Otter Creek at Ashland, Montana, July 2004. View is looking downstream from the gaging station. The stream at this location was frequently affected by backwater from a beaver dam, and gaging streamflow was difficult. During October 2004, the gage was moved upstream to a site unaffected by beavers.